at a glance

WHY DOES SPRAY FOAM TURN YELLOW OVER TIME?

SPRAY FOAM GOES THROUGH MANY COLOR CHANGES.

- Liquid components: color of motor oil.
- Initial mixing: brown.
- After rising: cream or white.

YELLOWING IS NATURAL AND CAUSED BY UV RAYS.

• If exposed to direct sunlight, foam will yellow.



UV RAYS CAN COMPROMISE PERFORMANCE.

- Cover your foam.
 - Physical cover (drywall)
 - Chemical cover (coatings)

BACK TO THE ARTICLE

REQUEST MY FREE QUOTE

